

Example 1 Identify all the zero force members in the truss shown, then draw a FBD of the truss with the zero force members removed.

